PACIFIC LUTHERAN UNIVERSITY CAMPUS FIRE SAFETY RIGHT -to- KNOW 2021 Fire Statistics: Log

Residential Building	Date Fire Reported	Time Fire Reported	Number of Fires	Location of Fire	Cause of Fire	Number of Injuries that Required Treatment at a Medical Facility		Value of Property Damage Caused by Fire	<u>Case</u> Number
N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A

PACIFIC LUTHERAN UNIVERSITY CAMPUS FIRE SAFETY RIGHT -to- KNOW 2020 Fire Statistics: Log

Residential Building	Date Fire Reported	Time Fire Reported	Number of Fires	Location of Fire	Cause of Fire	Number of Injuries that Required Treatment at a Medical Facility		Value of Property Damage Caused by Fire	<u>Case</u> Number
N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A

PACIFIC LUTHERAN UNIVERSITY CAMPUS FIRE SAFETY RIGHT -to- KNOW 2019 Fire Log

Residential Building	Date Fire Reported	Time Fire Reported	Number of Fires	Location of Fire	Cause of Fire	Number of Injuries that Required Treatment at a Medical Facility	Number of Deaths Related to Fire	Value of Property Damage Caused by Fire	<u>Case</u> Number
South Hall	3/22/2019	5:48 PM	1	residence hall kitchen, room 036	Oil overheated in skillet while cooking	0	0	NA	1

PACIFIC LUTHERAN UNIVERSITY CAMPUS FIRE SAFETY RIGHT -to- KNOW 2018 Fire Statistics: Log

Residential Building	Date Fire Reported	Time Fire Reported	Number of Fires	Location of Fire	Cause of Fire	Number of Injuries that Required Treatment at a Medical Facility	Number of Deaths Related to Fire	Value of Property Damage Caused by Fire	<u>Case</u> Number
None	NA NA	NA NA	NA	NA	NA	NA	NA	NA	NA

PACIFIC LUTHERAN UNIVERSITY CAMPUS FIRE SAFETY RIGHT -to- KNOW 2017 Fire Statistics: Log

Residential Building	Date Fire Reported	Time Fire Reported	Number of Fires	Location of Fire	<u>Cause of Fire</u>	Number of Injuries that Required Treatment at a Medical Facility	Number of Deaths Related to Fire	Value of Property Damage Caused by Fire	<u>Case</u> Number
Tingelstad Hall	11/3/2017	1:00 PM	1	Room 814	Combustible material (i.e. cardboard boxes) placed on top of electrical stove element that was inadvertently turned on caused the fire.	0	0	\$89,500	1